

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director Permitee: PacifiCorp

JON M. HUNTSMAN, JR. Governor GARY R. HERBERT Lieutenant Governor

Operator: ENERGY WEST MINING CO

Site: DEER CREEK MINE

Representatives Present During the Inspection:

Company Dennis Oakley Environmental Engineer

OGM Karl Houskeeper Environmental Scientist III

Address: PO BOX 310, HUNTINGTON UT 84528

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Mineral Ownership

Types of Operations

Permit Number:

Inspection Type:

Inspection Date:

Start Date/Time:

End Date/Time:

Inspection Report

Last Inspection: Wednesday, December 16, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Snowing, Temp. 25 Deg. F.

InspectionID Report Number: 2245

C0150018 **PARTIAL**

Tuesday, January 19, 2010

1/19/2010 8:30:00 AM

1/19/2010 12:00:00 PM

Accepted by: jhelfric

1/25/2010

| ✓ Federal | ✓ Underground |
|------------------|---------------|
| ✓ State | ☐ Surface |
| ☐ County | Loadout |
| ✓ Fee | Processing |
| Other | Reprocessing |

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Current Acreages

19,740.78 **Total Permitted** 98.05 **Total Disturbed** 0.60 Phase I Phase II Phase III

Inspector's Signature:

Date

Tuesday, January 19, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 19, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | | Evaluated | Not Applicable | Comment | Enforcement |
|------|---|-----------|----------------|---------|-------------|
| 1. | Permits, Change, Transfer, Renewal, Sale | | | | |
| 2. | Signs and Markers | ✓ | | ✓ | |
| 3. | Topsoil | | | | |
| 4.a | Hydrologic Balance: Diversions | ✓ | | ✓ | |
| 4.b | Hydrologic Balance: Sediment Ponds and Impoundments | ✓ | | | |
| 4.c | Hydrologic Balance: Other Sediment Control Measures | | | | |
| 4.d | Hydrologic Balance: Water Monitoring | | | | |
| 4.e | Hydrologic Balance: Effluent Limitations | | | | |
| 5. | Explosives | | | | |
| 6. | Disposal of Excess Spoil, Fills, Benches | | | | |
| 7. | Coal Mine Waste, Refuse Piles, Impoundments | | | | |
| 8. | Noncoal Waste | ✓ | | ✓ | |
| 9. | Protection of Fish, Wildlife and Related Environmental Issues | | | | |
| 10. | Slides and Other Damage | | | | |
| 11. | Contemporaneous Reclamation | | | | |
| 12. | Backfilling And Grading | | | | |
| 13. | Revegetation | | | | |
| 14. | Subsidence Control | | | | |
| 15. | Cessation of Operations | | | | |
| 16.8 | a Roads: Construction, Maintenance, Surfacing | | | | |
| 16.t | Roads: Drainage Controls | | | | |
| 17. | Other Transportation Facilities | | | | |
| 18. | Support Facilities, Utility Installations | | | | |
| 19. | AVS Check | | | | |
| 20. | Air Quality Permit | | | | |
| 21. | Bonding and Insurance | | | | |
| 22. | Other | | | | |

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 19, 2010

Page 3 of 3

2. Signs and Markers

The Mine ID signs are located at the points of public access to the permit area and contained the necessary information.

4.a Hydrologic Balance: Diversions

Diversions are snow covered. Care has been taken not to push snow into the diversions.

8. Noncoal Waste

Noncoal waste had been recently hauled off the mine site. A small amount remained in the approved storage facility.